


CT2015A CABLE CROSSOVER

REVISED:Jun.18,2013

PART LIST

ITEM	QTY	DESCRIPTION	ITEM	QTY	DESCRIPTION
1	2	WEIGHT STACK FRAME	43	2	TWO SNAP LINKS
2	2	SUPPORT FRAME	44	2	FLANGE NUT 1/2"-13
3	1	UPPER BOOM CROSSMEMBER	45	2	HX-SHCS 0.5-13x1.375x1.375-N
4	2	LOWER CABLE CROSSOVER BASE FRAME	46	2	COIL CHAIN
5	2	1.75 SQ. TUBING FOR SLIDE POSITION	47	2	SELECTOR PINS w/COIL
6	1	L ADJUSTABLE SWIVEL SLIDE ASSEMBLY	48	2	CABLE SUBASSEMBLY
7	1	R ADJUSTABLE SWIVEL SLIDE ASSEMBLY			
8	2	SELF CENTERING SWIVEL ASSEMBLY			
9	4	HANDRAIL			
10	2	WEIGHT STACK SHIELD			
11	4	WEIGHT STACK FRAME SHIELD			
12	2	TOP PLATE PULLEY BRACKET			
13	16	PULLEY ASSEMBLY 4.5			
14	2	PUSH PULL PIN 1/2 X 2 9/16			
15	6	4x6 FOOT PAD			
16	4	RADIAL BEARING			
17	18	FW 0.5			
18	4	HBOLT 0.5000-13x4.25x1.25-N			
19	4	HBOLT 0.5000-13x4x1.25-N			
20	2	HBOLT 0.5000-13x2.5x1.25-N			
21	8	HJNUT 0.5000-13-D-N			
22	60	FW 0.375			
23	2	HBOLT 0.3750-16x4.5x1-N			
24	4	HBOLT 0.3750-16x2.75x1-N			
25	2	HBOLT 0.3750-16x2.5x1-N			
26	2	HBOLT 0.3750-16x2.25x1-N			
27	14	HBOLT 0.3750-16x2x1-N			
28	8	HBOLT 0.3750-16x3.5x1-N			
29	28	HJNUT 0.3750-16-D-N			
30	16	FW 0.3125			
31	8	SBHCSCREW 0.3125-18x0.75-HX-N			
32	8	HNUT 0.3125-18-D-N			
33	20	SBHCSCREW 0.25-20x0.3125-HX-N			
34	4	WEIGHT STACK GUIDE ROD			
35	2	WEIGHT STACK PIN 15 HOLE			
36	4	RUBBER DONUT			
37	28	10 LB WEIGHT STACK			
38					
39	2	TOP WEIGHT			
40	2	TRICEP PUSHDOWN BAR			
41	1	R 3.5LB ADD-ON WEIGHT SUPPORT BAR (WEIGHT STACK HALF)			
42	2	HANDLE			

CABLE ROUTING DETAIL



SEE NEXT PAGE FOR  
EXPLODED VIEW DIAGRAM



**USE CAUTION  
WHEN WORKING  
WITH WEIGHT  
STACK 1**

